

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

U.S. NAVAL BASE, PEARL HARBOR, COAL DOCK
(U.S. Naval Base, Pearl Harbor, Naval Shipyard, Facility No. O-1,
Repair Wharf)
End of South Avenue near Dry Dock No. 4
Pearl Harbor
Honolulu County
Hawaii

HABS HI-517

INDEX TO BLACK AND WHITE PHOTOGRAPHS

David Franzen, photographer, July 2001

HI-517-1	Overview of southern coastline looking towards Piers O-1, O-2, and O-3, Facility 177 to left, Dry Dock No. 4 in center
HI-517-2	Overview of Coal Dock, taken from the ocean, view facing northeast
HI-517-3	Length of underside of Coal Dock, taken from the ocean, view facing north
HI-517-4	View of top of deck of Pier O-1
HI-517-5	View of top of deck of south end of curved section, later extension of width of the curve (transverse beams and 4' wide walkway) to the right of the photo
HI-517-6	View of pier supports from the water's edge
HI-517-7	View of intact south end curved section taken from the ocean, view facing west-southwest
HI-517-8	Cut end of north end curved portion, taken from the ocean, view facing south, vacated Facility 831 on top of deck
HI-517-9	Detail of cur end of north end curved portion of Coal Dock, taken from the ocean, view facing south